

{In Archive} Fw: GP Crossett Brf Fct Sheet, Outfall Descriptions, Discharge flow and Outfall Locations (Koch Industries - EJ issue in Arkansas)

Philip Crocker to: Matt Hubner 10/19/2011 12:07 PM

From: Philip Crocker/R6/USEPA/US

To: Matt Hubner/R6/USEPA/US@EPA

Archive: This message is being viewed in an archive.

fyi

----- Forwarded by Philip Crocker/R6/USEPA/US on 10/19/2011 12:06 PM -----

From: William Honker/R6/USEPA/US

To: Jane Watson/R6/USEPA/US@EPA, Philip Crocker/R6/USEPA/US@EPA, "Jeannine Hale"

<Hale.Jeannine@epamail.epa.gov>, Israel Anderson/R6/USEPA/US@EPA

Date: 10/19/2011 10:28 AM

Subject: Fw: GP Crossett Brf Fct Sheet, Outfall Descriptions, Discharge flow and Outfall Locations (Koch

Industries - EJ issue in Arkansas)

FYI.

William K. (Bill) Honker, P.E.
Senior Policy Advisor for Coastal Restoration, Climate Change, and Public Outreach
Deputy Director, Water Quality Protection Division
EPA Region 6 - Dallas, TX
Phone 214-665-3187
Fax 214-665-7373
Cell 214-551-3619

---- Forwarded by William Honker/R6/USEPA/US on 10/19/2011 10:28 AM -----

From: Paulette Johnsey/R6/USEPA/US

To: William Honker/R6/USEPA/US@EPA, Claudia Hosch/R6/USEPA/US@EPA

Cc: Jerry Saunders/R6/USEPA/US@EPA

Date: 10/19/2011 10:01 AM

Subject: Fw: GP Crossett Brf Fct Sheet, Outfall Descriptions, Discharge flow and Outfall Locations (Koch

Industries - EJ issue in Arkansas)

Bill - I went to the facility and walked/rode the full treatment down to the lake. I'm sure your folks are very familiar with this facility but here are a couple historical things about the facility I learned that might help as you discuss with our and HQ ej officials. The facility does (or did a few yrs back) have a log spraying area just below the neighborhood in question. It is the bare area just west of the round trickling filter you can see just west of the main plant areas. The old pond that now just has a channel through the middle ends with a cascade aeration down to a lower part of the creek(or 'treatment canal') that takes it to the aeration basin. Those aerators are not that old - far fewer of them when I was there.

Also there used to be a serious acid problem. When I was there, there used to be a process ditch on the east side of the plant that drained acid from the pulping units, Acid in the ditch was so strong it burned you nose to be near it. across the road from the ditch was a trailer park. When I remarked about the acid fumes and the rust on the trailers he said they had to replace the peoples AC window units once a year because the rusted out so fast.

The people that live in that town have been breathing corrosive fumes for years. It is not necessarily the aeration from the treatment - but it may be a serious contributing factor. Don't know. If you have any questions about what it looks like on the ground - I'll be glad to tell you. It made quite an impression on me.

Paulette Johnsey

Chief, NPDES Compliance Section USEPA Region 6
Direct Phone 214 665-7521

---- Forwarded by Paulette Johnsey/R6/USEPA/US on 10/19/2011 09:45 AM -----

From: Jerry Saunders/R6/USEPA/US

To: "Carol Peters" < Peters. Carol@epamail.epa.gov >, "Paulette Johnsey"

<Johnsey.Paulette@epamail.epa.gov>, "Jana Harvill" <Harvill.Jana@epamail.epa.gov>

Date: 10/19/2011 07:44 AM

Subject: Fw: GP Crossett Brf Fct Sheet, Outfall Descriptions, Discharge flow and Outfall Locations (Koch

Industries - EJ issue in Arkansas)

Sent by EPA Wireless Email Services William Honker

---- Original Message ----From: William Honker

Sent: 10/18/2011 11:55 AM CDT

To: Jeannine Hale; Deborah Ponder; Israel Anderson

Cc: Stephen Gilrein; Jerry Saunders; David Garcia; Myron Knudson

Subject: Fw: GP Crossett Brf Fct Sheet, Outfall Descriptions, Discharge

flow and Outfall Locations (Koch Industries - EJ issue in Arkansas)

FYI, here's a lot of info on the GP Crossett NPDES permit. As we discussed yesterday, it would appear that airborne contaminants could be originating from WWTP process units (and/or other process units at the facility). However, any such air emissions would be regulated by CAA permits, not the NPDES permit.

William K. (Bill) Honker, P.E.

Senior Policy Advisor for Coastal Restoration, Climate Change, and Public Outreach

Deputy Director, Water Quality Protection Division

EPA Region 6 - Dallas, TX Phone 214-665-3187 Fax 214-665-7373 Cell 214-551-3619

----- Forwarded by William Honker/R6/USEPA/US on 10/18/2011 11:48 AM -----

From: Michael Tillman/R6/USEPA/US
To: William Honker/R6/USEPA/US@EPA

Cc: Claudia Hosch/R6/USEPA/US@EPA, Brad Crawford/R6/USEPA/US@EPA, Matt

Hubner/R6/USEPA/US@EPA, Jana Harvill/R6/USEPA/US@EPA

Date: 10/18/2011 11:34 AM

Subject: Fw: GP Crossett Brf Fct Sheet, Outfall Descriptions, Discharge flow and Outfall Locations (Koch

Industries - EJ issue in Arkansas)

Bill,

In response to your inquiry, I have updated the attached draft brief sheet, Outfall Description Summary, excerpts from the Application, and Google Earth Photos relative to Penn Street, GP Crossett, approximation of Process Discharge Flows and Outfall locations. I hope you find this information adequate.

Specifically, NPDES permits do not regulate air emissions from domestic or industrial wastewater treatment plants only wastewater discharges. I would assume any necessary air permits would be issued under the Clean Air Act (CAA). A quick look at the GP Crossett Permit application indicates that the facility is operating under 3 air permits. Permit Nos.:

597-AOP-R12 736-AOP-R6 1177-AOP-R8

Also attached is the latest documentation I have from Ecosystems regarding restablishing designated uses on Coffee Creek and Mossy Lake (UAA update 3/17/11).

If you have further questions, or need additional information, please let me know.

Mike Tillman (6WQ-PO) Arkansas / Texas - State NPDES Coord. U.S. EPA Region 6 1445 Ross Ave. Dallas, TX 75202 phn. 214-665-7531, fax. 214-665-2191

Confidentiality Warning:

This e-mail may be privileged and/or confidential, and the sender does not waive any related rights and obligations. It is intended for the named recipient(s) only. Any distribution, use or copying of this e-mail or the information it contains by other than an intended recipient is unauthorized. If you received this e-mail in error, please advise me (by return e-mail or otherwise) immediately and do not duplicate it or disclose its contents to anyone.

-----Forwarded by Michael Tillman/R6/USEPA/US on 10/18/2011 11:18AM -----

To: Michael Tillman/R6/USEPA/US@EPA From: Claudia Hosch/R6/USEPA/US

Date: 10/17/2011 02:36PM

Subject: Fw: Koch Industries - EJ issue in Arkansas

fyi

----- Forwarded by Claudia Hosch/R6/USEPA/US on 10/17/2011 02:34 PM -----

From: William Honker/R6/USEPA/US

To: hosch.claudia@epa.gov

Cc: Philip Crocker/R6/USEPA/US@EPA, Brad Crawford/R6/USEPA/US@EPA, Jane

Watson/R6/USEPA/US@EPA Date: 10/17/2011 01:11 PM

Subject: Fw: Koch Industries - EJ issue in Arkansas

Claudia/Brad.

Could you check on where the discharge point(s) is/are for the GP permit? As I recall, the company has maintained that they own all the property from their plant site to Mossy Lake. Looking at Google Earth, it appears that there are WW treatment units scattered out for several miles southwest of the plant site. Some of these appear to have aerators in them. It may be that volatiles from their WWTP are impacting the Penn Road neighborhood to the north. If so, how are air emissions from GP's WWTP regulated?

William K. (Bill) Honker, P.E.
Senior Policy Advisor for Coastal Restoration, Climate Change, and Public Outreach
Deputy Director, Water Quality Protection Division
EPA Region 6 - Dallas, TX
Phone 214-665-3187
Fax 214-665-7373
Cell 214-551-3619

FYI. This is re GP Crossett. Do we have a fact sheet or two we can share with Jeannine?

William K. (Bill) Honker, P.E.
Senior Policy Advisor for Coastal Restoration, Climate Change, and Public Outreach
Deputy Director, Water Quality Protection Division
EPA Region 6 - Dallas, TX
Phone 214-665-3187
Fax 214-665-7373
Cell 214-551-3619

---- Forwarded by William Honker/R6/USEPA/US on 10/14/2011 12:42 PM -----

From: Jeannine Hale/R6/USEPA/US

To: Miguel Flores/R6/USEPA/US@EPA, William Honker/R6/USEPA/US@EPA, John Blevins/R6/USEPA/US@EPA, Stephen Gilrein/R6/USEPA/US@EPA, Jerry Saunders/R6/USEPA/US@EPA, Esteban Herrera/R6/USEPA/US@EPA
Cc: Layla Mansuri/R6/USEPA/US, Deborah Ponder/R6/USEPA/US@EPA, Sam Coleman/R6/USEPA/US@EPA, Pam Phillips/R6/USEPA/US@EPA, Israel Anderson/R6/USEPA/US@EPA, Suzanne Murray/R6/USEPA/US@EPA, Scott

McDonald/R6/USEPA/US@EPA, William Luthans/R6/USEPA/US@EPA, James Leathers/R6/USEPA/US@EPA

Date: 10/13/2011 05:07 PM

Subject: Koch Industries - EJ issue in Arkansas

Please watch the video at:

http://www.huffingtonpost.com/2011/10/12/arkansas-koch-industries-plant-high-rates-of-cancer n 1007 148.html

Israel tells me that he has previously coordinated with folks and ADEQ went out to investigate.

After seeing the video below, it is difficult to believe there is no water quality problem - the oil is visible in the stream.

I am asking that Region 6 Divisions do the following:

- 1- share any reports from the state with OEJTA
- 2- let us know if/when/how your Division plans to look into the allegations about air and water pollution, independent of the state
- 3- include us, to extent possible, in any discussions

We are planning to visit this community, gather more information, and will make contacts regarding the health issues.

Jeannine Hale, Director
Office of Environmental Justice and Tribal Affairs
Region VI EPA (6RA-DA)
1445 Ross Avenue
Dallas, Texas 75202
Tel. 214.665.2136 (office)
Cell 214.864.6134
Fax 214.665.2124

This document may contain attorney work product, attorney-client communications, or other information that is privileged/confidential. Please do not forward, copy, disclose or distribute this document or any part thereof except as authorized by Sender or other agency legal counsel.

---- Original Message -----

From: Richard Windsor

Sent: 10/13/2011 12:30 PM EDT
To: Lisa Garcia; Al Armendariz
Subject: EJ issue in Arkansas?

http://www.huffingtonpost.com/2011/10/12/arkansas-koch-industries-plant-high-rates-of-cancer n 1007 148.html

Heads up

[attachment "Outfall Descriptions - Excerpt from GP Crossett NPDES Permit Fact Sheet.docx" deleted by Paulette Johnsey/R6/USEPA/US] [attachment "GP Crossett Brf Sht.10-17-11.doc" deleted by Paulette Johnsey/R6/USEPA/US] [attachment "GP Crossett Discharge App Excerpts - 2-24-09.pdf.docx" deleted by Paulette Johnsey/R6/USEPA/US] [attachment "GP Crossett - South Penn St.jpg" deleted by Paulette Johnsey/R6/USEPA/US] [attachment "GP Crossett - Crossett Ark.jpg" deleted by Paulette Johnsey/R6/USEPA/US] [attachment "GP Crossett - Discharge Flow 1.jpg" deleted by Paulette Johnsey/R6/USEPA/US] [attachment "GP Crossett - Discharge Flow 2.jpg" deleted by Paulette Johnsey/R6/USEPA/US] [attachment "GP Crossett - Discharge Flow Ttl.jpg" deleted by Paulette Johnsey/R6/USEPA/US] [attachment "GP Crossett UAA updt.3-17-11.docx" deleted by Paulette Johnsey/R6/USEPA/US]